

WA-I- 514     Frame House

Mid-20th century

Hagerstown Vicinity

Private

The one-story frame house is a early 20th century cottage style structure. It is L-shaped with a projecting hipped roof bay along the main facade creating the ell in the house. The main section is also hipped roofed with a flue located at the center portion of the roof. The main facade has a three-section window in the projecting bay and a doorway flanked by a window on either side in the main section. While the house is basically un-elaborate except for brackets on the roof eaves, the house presents a overall ornamental appearance through its shape and use of the hipped roof.

Magi No.

DOE yes no

# Maryland Historical Trust

## State Historic Sites Inventory Form

### 1. Name (indicate preferred name)

historic Frame house

and/or common

### 2. Location

street & number east side of Rt. 65, .16 mile south of I-70 not for publicationcity, town Hagerstown x vicinity of congressional district sixthstate Maryland county Washington

### 3. Classification

Category	Ownership	Status	Present Use	
<u>district</u>	<u>public</u>	<u>occupied</u>	<u>agriculture</u>	<u>museum</u>
<u>building(s)</u>	<u>private</u>	<u>unoccupied</u>	<u>commercial</u>	<u>park</u>
<u>structure</u>	<u>both</u>	<u>work in progress</u>	<u>educational</u>	<u>private residence</u>
<u>site</u>	<b>Public Acquisition</b>	<b>Accessible</b>	<u>entertainment</u>	<u>religious</u>
<u>object</u>	<u>in process</u>	<u>yes: restricted</u>	<u>government</u>	<u>scientific</u>
	<u>being considered</u>	<u>yes: unrestricted</u>	<u>industrial</u>	<u>transportation</u>
	<u>not applicable</u>	<u>no</u>	<u>military</u>	<u>other:</u>

### 4. Owner of Property (give names and mailing addresses of all owners)

name

street &amp; number telephone no.:

city, town state and zip code

### 5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liberstreet & number Washington Street foliocity, town Annapolis state Maryland

### 6. Representation in Existing Historical Surveys

title

date \_\_\_\_\_ \_\_\_\_\_ federal \_\_\_\_\_ state \_\_\_\_\_ county \_\_\_\_\_ local

depository for survey records

city, town state

## 7. Description

Survey No. WA-I-~~494~~ 514

<b>Condition</b>		<b>Check one</b>	<b>Check one</b>	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site	
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The one-story frame house is a early 20th century cottage style structure. It is L-shaped with a projecting hipped roof bay along the main facade creating the ell in the house. The main section is also hipped roofed with a flue located at the center portion of the roof. The main facade has a three-section window in the projecting bay and a doorway flanked by a window on either side in the main section. While the house is basically unelaborate except for brackets on the roof eaves, the house presents a overall ornamental appearance through its shape and use of the hipped roof.

This property is located on the east side of Rt. 65, .16 mile south of I-70. It is situated in a group of structures on  $\frac{1}{4}$  to  $\frac{1}{2}$  acre lots dating from the mid-29th century to the present time.

The main facade of the frame house is marked by numerous windows. The projecting bay has a three-section window with each section containing a six-over-six pane window. Above these windows is a small attic vent. The main section of the facade is enclosed under a porch roof that runs along the same plane as the projecting L. The porch is concrete and the railing has a cross-shaped bannister. The main doorway has a nine-pane glass section and six-over-six windows on each side of it. The gable ends have two windows of unequal size and a small window in the attic. The roof is covered in an ornamental pattern of asphalt shingles.

There are no significant outbuildings on the property.

## 8. Significance

Survey No. WA-I-494 514

Period	Areas of Significance—Check and justify below			
___ prehistoric	___ archeology-prehistoric	___ community planning	___ landscape architecture	___ religion
___ 1400–1499	___ archeology-historic	___ conservation	___ law	___ science
___ 1500–1599	___ agriculture	___ economics	___ literature	___ sculpture
___ 1600–1699	___ architecture	___ education	___ military	___ social/
___ 1700–1799	___ art	___ engineering	___ music	___ humanitarian
___ 1800–1899	___ commerce	___ exploration/settlement	___ philosophy	___ theater
___ 1900–	___ communications	___ industry	___ politics/government	___ transportation
		___ invention		___ other (specify)

### Specific dates

### Builder/Architect

check: Applicable Criteria: \_\_\_ A \_\_\_ B \_\_\_ C \_\_\_ D  
and/or

Applicable Exception: \_\_\_ A \_\_\_ B \_\_\_ C \_\_\_ D \_\_\_ E \_\_\_ F \_\_\_ G

Level of Significance: \_\_\_ national \_\_\_ state \_\_\_ local

Prepare both a summary paragraph of significance and a general statement of history and support.

Based on the MHT Survey Matrix, this is a minimal site due to its recent date of construction.

## 9. Major Bibliographical References

Survey No. WA-I-~~494~~ 514

## 10. Geographical Data

**Acreage of nominated property** \_\_\_\_\_

**Quadrangle name** \_\_\_\_\_

**Quadrangle scale** \_\_\_\_\_

**UTM References** do NOT complete UTM references

**A**

Zone Easting Northing

**B**

Zone Easting Northing

The figure shows three separate coordinate axes. The first axis is labeled 'Zone' and has two tick marks. The second axis is labeled 'Easting' and has five tick marks. The third axis is labeled 'Northing' and has five tick marks. Each axis is represented by a horizontal line with vertical tick marks extending upwards.

**c**

D

E | | | | |

F 

**G**

H | | | | | | | | | |

### Verbal boundary description and justification

**List all states and counties for properties overlapping state or county boundaries**

state	code	county	code
-------	------	--------	------

state	code	county	code
-------	------	--------	------

**11. Form Prepared By**

**name/title** Joe Getty

**organization** Maryland Historical Trust

**date** May 1983

**street & number** 21 State Circle

**telephone**

city or town      Annapolis

state Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust  
Shaw House  
21 State Circle  
Annapolis, Maryland 21401  
(301) 269-2438



1. Frame House    WA-I-494 514
2. Washington County, Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. West Elevation; camera facing east
7. 1/1